


IN-CEILING SPEAKER INSTALLATION INSTRUCTIONS



Troubleshooting

Problem	Possible cause	Solution
Bass too weak	Connection cable wrongly connected	Check connection cable and reconnect where necessary